	SPE RESPONSE F	OR CERTIFICATE OF CORRECTION
		Paper No.:
DATE :	02/28/06	
TO SPE OF :	ART UNIT 2834	
SUBJECT :	: Request for Certificate of Correction on Patent No.: 10/758109 6967424	
A response is re	equested with respect to the	e accompanying request for a certificate of correction.
Palm location ?	·	rith file, within 7 days to: rrection Branch – South Tower – 9A22 ployee (named below) via PUBSCofC Team in
With respect to patent read as s		correcting Office and/or Applicant's errors, should the orrection (COCIN)? No new matter should be introduced, nor hanged.
Thank You For Y	our Assistance	Angela Green Certificates of Correction Branch Tel. No. 703-305-9380 ext. 123
The request fo	, -	entified correction(s) is hereby:
A A	pproved	All changes apply.
_ A	pproved in Part	Specify below which changes do not apply.
0 D	enied	State the reasons for denial below.
Comments:		
		TRAN NGUYEN/ PRIMARY EXAMINEI

PTOL-306 (REV. 7/03)

SPE Art Unit
U.S. DEPARTMENT OF COMMERCE Patent and Trademark Office

PTO/SB/44 (04-05) Approved for use through 04/30/2007. OMB 0651-0033 U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Inder the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 3

PATENT NO.

: 6,967,424

APPLICATION NO.: 10/758,109

ISSUE DATE

November 22, 2005

INVENTOR(S)

Vladimir Vladimirovich Popov

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the drawings:

in Figure 1 show the angles indicated as 2.5, 7.5 and 12.5 degrees measured between the center line of the slots 12 and the center line of the shallow notches 20. A corrected Figure 1 is shown on page 2 of 3;

in Figure 2a show groove 200 to be in the same tangential position with regard to the slots of laminations 10-1, 10-2, 10-3, 10-4, 10-5 and 10-6. A corrected Figure 2a is shown on page 3 of 3; and

in Figure 2b show groove 201 to be in the same tangential position with regard to the slots of laminations 10-1, 10-2, 10-3, 10-4, 10-5 and 10-6. A corrected Figure 2b is shown on page 3 of 3.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Duane Morris LLP 1667 K Street, N.W. Suite 700 Washington, DC 20006

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.



ATTORNEY DOCKET NO. BOE01 043

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re the Patent of Vladimir Vladimirovich POPOV

Serial No.: 10/758,109

Patent No.: 6,967,424

Filed: January 16, 2004

Issue Date: November 22, 2005

Title: ROTOR ASSEMBLY AND STATOR ASSEMBLY FOR AN ELECTRICAL

MACHINE

PURSUANT TO 37 C.F.R. § 1.323

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee requests a certificate of correction for the subject patent to reflect errors identified in Figures 1, 2a and 2b of the subject patent.

The errors are of a minor nature or character and occurred in good faith.

Correction thereof does not involve such changes in the patent as would constitute new matter or would require re-examination.

Attached hereto, in duplicate, is Form PTO/SB/44 with at least one copy being suitable for printing. Attached hereto are "Replacement sheets" for amended Figures 1, 2a and 2b and "Annotated marked-up sheets" showing the minor amendments to Figures 1, 2a and 2b.

Applicant submits herewith the requisite fee pursuant to 37 C.F.R. § 1.323 and

- ZULO

respectfully solicits issuance of a corrected patent or in the alternative, issuance of a certificate of correction reflecting the corrections identified in the attached PTO/SB/44 form and Figures 1, 2a and 2b replacement sheets.

Respectfully submitted,

Mark C. Comtois,

Reg. No. 46,285

D. Joseph English

Reg. No. 42,514

Patrick D. McPherson Reg. No. 46,255

DUANE MORRIS LLP 1667 K Street, N.W., Suite 700 Washington, D.C. 20006 Telephone: (202) 776-7800

Telephone: (202) 776-7800 Telecopier: (202) 776-7801

Dated: February 13, 2006